1.

2.

3.

4.

5.

6.

HISTORIC NAME/FUNCTION:

ADDRESS/LOCATION:

TOWN/NEAREST TOWN:

7. ADDITIONAL FORMS USED:

Form:

8. SURVEYOR INFORMATION:

Principal Investigator name:

Principal Investigator signature:

Surveyor name:

Organization:

MAIN TYPE OF RESOURCE:

MAIN FUNCTION OF PROPERTY:

CRS 2 Main Building Form CRS 3 Secondary Building Form CRS 4 Archaeological Site Form CRS 5 Structure (Building-Like) Form CRS 6 Structure (Land Feature) Form

CRS 8 Landscape Elements Form

CRS 14 Potential District Form

CRS 7 Object Form

CRS 9 Map Form

PROJECT TITLE/ REASON FOR SURVEY (if applicable):

DELAWARE STATE HISTORIC PRESERVATION OFFICE

CULTURAL RESOURCE SURVEY PROPERTY IDENTIFICATION FORM

building

landscape

15 THE	GREEN, DOVER, DE 19901
/EY FORM	CRS# K-7276 SPO Map Hundred Each DOVER Quad Other
u Port	
VER DE	vicinity?
structure district	site object
ESIDENLE	
plicable): SMEWAW PR	PLACEMENT POTELF (DEL ROT)
List property types:	
House	
N/A	
EATHER YOST	
POFFRON HEND	Zy
1 1 1 1 1	1

۵.	OTHER	NOTES	ΩR	OBSER\	VΔT	CIONS
ч.	UIHER	MOLES	UK	ODSER	4 M I	

crs#1-7226

overgrewn

10. STATE HISTORIC CONT plan(s)):	EXI FRAMEWORK (check	all appropriate boxes; refer to state management
a) Time period(s)	Pre-European C Paleo-Indian Archaic Woodland I Woodland II	contact
	1880-1940∀ Urbanization	nd Frontier Settlement d Durable Occupation
b) Geographical zone	Coastal	
c) Historic period theme	e(s)	
	Agriculture Forestry Trapping/Hunting Mining/Quarrying Fishing/Oystering Manufacturing Retailing/Wholesaling Finance Professional Services	 □ Transportation and Communication ☑ Settlement Patterns and Demographic Changes □ Architecture, Engineering and Decorative Arts □ Government □ Religion □ Education □ Community Organizations □ Occupational Organizations □ Major Families, Individuals and Events

DELAWARE STATE HISTORIC PRESERVATION OFFICE 15 THE GREEN, DOVER, DE 19901

CULTURAL RESOURCE SURVEY MAIN BUILDING FORM

CRS# K-7226

1.	ADDRESS/LOCATION: 584 N. DuPONT HWY
2.	FUNCTION(S): historic MOUSE current HOUSE
3.	YEAR BUILT: 1945 CIRCA?: ARCHITECT/BUILDER: UNCLOS
4.	STYLE OR FLOOR PLAN: MINIMAL TRADITIONAL
5.	INTEGRITY: original site 🖾 moved 🗌
	if moved, from where other location's CRS # year
	list major alterations and additions with years (if known) a. REAL ADDITION year UNKNOWN
	b
5.	CURRENT CONDITION: excellent good fair poor
7.	DESCRIPTION: (Describe the resource as completely as possible. Use N/A for not applicable; leave no blanks.)
	a. Overall shape: LINEAR Stories: \ Additions: REAL PORCH
	b Structural system (if known): FRAME & MASONEY
	c. Foundation: materials: Beck basement: full [] partial [] not visible [] no basement []
	d. Exterior walls (original if visible& any subsequent coverings):
	ROMAN BUCK & STUCO
	e. Roof: shape: HLPPED materials: CLEDAL SHLVYLE
	materials: ພອກຂາກ ການ ເພື່ອການ ເພື່ອກາ
	dormers: SHEO ROOF
	chimney: location(s): INTERIOR - BRICK
3.	DESCRIPTION OF ELEVATIONS:
	a. Facade: Direction: CAST EXCUATION
	1) Bays 🧽 2) Windows
	fenestration ASYMMETRICAL
	type 6/6 VIDYL SASHES & 64-LIGHT GLASS BLOCK WURDOW
	trim woop shutters
	Shutters Howk

```
Facade (cont'd)
                  ONE
        Door(s)
          location CENTER OF FACIANCE
          type
                  MUMMUA
          trim
                  WOOD W/ ROWDED PROMENT ABOUT
    4)
        Porch(es)
                  NONE
    Side: Direction:
                   HORTH
    1)
        Bays
        Windows
    2)
          fenestration
          type
                        NOT VISIBLE DUE TO WERGROWTH
          trim
          shutters
                                OF VEGETATION
    3)
        Door(s)
          location
          type
          trim
        Porch(es)
   Side: Direction: SOUTH ELENATION
    1)
        Bays
    2)
        Windows
          fenestration ASYMMETRICAL
                    2/2 VINYL SASH
          type
          trim
                   NONE
          shutters
                   NONE
   3)
        Door(s)
                  2nd BAI FROM DAST
          location
          type
                  ALUMINUM
          trim
                  NUNE
   4)
        Porch(es)
                   NONE
                   WEST ELEVATION
   Rear: Direction:
d.
        Bays
                       3
       Windows
   2)
          fenestration REGULARIA SPACED
                   1st FLOOR, 6/6 UNYL SASH 200 FLOOR,
          trim
                   いらんじ
          shutters
                   NONE
   3)
       Door(s)
          location
                    NOT VISIBLE - INSIDE QUELOSED PURCH
         type
         trim
       Porch(es)
                 ENCLOSED WITH LOUDERD, 4-PANEMETAL CASBURNT WHOOW)
```

9. INTERIOR: NA

10. LANDSCAPING:

Overgrown

11. OTHER COMMENTS: JACANT?

CULTURAL R MAP FORM

DELAWARE STATE HISTORIC PRESERVATION OFFICE 15 THE GREEN, DOVER, DE 19901


CULTURAL RESOURCE SURVEY MAP FORM

CRS# K-7 226

1.	ADDRESS/LOCATION:	584	N. DuPout Hwy
2.	NOT FOR PUBLICATION	reason: _	
3.	LOCATION MAP:		
	Indicate position of resource in re	elation to ge	eographical landmarks such as streams and crossroads.

(attach section of USGS quad map with location marked or draw location map)

INDICATE NORTH ON SKETCH



INDICATE NORTH ON PLAN

DELAWARE STATE HISTORIC PRESERVATION OFFICE

PHOTOGRAPHIC INVENTORY - CONTACT SHEET

Negative location (if other than SHPO)			
Photo Roll # 3		Surveyor Heather Yost Date 9/24/2003	
Frame #	CRS#	Description of view	
	K-7226	S MAIN FACADE	
2_	K-7226	Door	
3_	K-7226	NW MAIN FACADE & GARAGE	
4	K-7226	PW MAIN FACADE	
5_	K-7226	SIDE LOOKING N	
6	K-7226	REAL & W. ELEVATION	
7	K-7226	SE REAR & W. ELEVATION	
8	K-7226	NE LEAR & W. ELEVATION	
9_	K-7226	GUKS WINDOW DETAIL	
<u>-</u>			